

## VEHICLE INSPECTION REPORT

**SF16CLP**

### Vauxhall Movano 2.3 CDTi BiTurbo ecoFLEX H1 Crew Cab Tipper 136ps

#### Inspection

Serious Damage? No

#### Vehicle

VAT Plus VAT

V5 Present

#### Details

Reg. date 27/07/2016

Year 2016

Mileage 40,018 Miles Not Warranted

Fuel Type Diesel

Colour WHITE

VIN W0LMSP4Y2GB107925

Body Style Tipper Double Cab

Keys 1

MOT Due 08/03/2026

CAP Clean £6,225.00

CAP Average £5,200.00

CAP Below £3,850.00

Gearbox MANUAL

Gears 6

Doors 2

Steering Combi Standard Axle

Rear Suspension Steel

#### Tyres

NSF

NSR

OSF

OSR

Spare


## Features

- Radio/CD
- Front electric windows
- Drivers airbag
- Central locking
- Cloth seat trim


## Photos







## Condition Check



## Damage Photos



1: Seat Base Cover osf  
Torn  
Over 3mm



2: Sill os  
Rusted  
Over 5mm





3: Bonnet  
Dented  
With Paint Damage



4: Wing osf  
Dented  
With Paint Damage



5: Door osf  
Dented  
With Paint Damage



6: Qtr Panel osr  
Dented  
With Paint Damage



7: Tailgate  
Dented  
With Paint Damage



8: Qtr Panel nsr  
Dented  
With Paint Damage



9: Door nsf  
Dented  
With Paint Damage



10: Sill ns  
Dented  
With Paint Damage



11: Wing nsf  
Dented  
With Paint Damage

### Interior

| Carpet Condition         |                    | Upholstery Condition                           |               |
|--------------------------|--------------------|------------------------------------------------|---------------|
| Seat Condition           | Average<br>Average | Odour                                          | Average<br>No |
| Engine Runs              | OK                 | Gearbox 1st and Reverse Test                   | OK            |
| Brakes                   | OK                 | Clutch Slip Test from Static                   | OK            |
| Turbo Boosting           | OK                 | Gearbox Static Gear Selection (engine running) | OK            |
| Parking Brake            | OK                 | No Excessive Smoking                           | OK            |
| EML light illuminated    | OK                 | Oil warning light illuminated                  | OK            |
| Airbag light illuminated | OK                 | DPF light illuminated                          | OK            |
| ABS light illuminated    | OK                 | Service indicator light illuminated            | OK            |

Windows

OK

Radio

OK

Steering

OK