

VEHICLE INSPECTION REPORT

BT15MWL

Iveco Daily 70-170

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 08/06/2015

Year 2015

Mileage 63,487 Miles
Warranted

Fuel Type Diesel

GVW 7000kg

Colour WHITE

VIN ZCFC270C405011511

Body Style Panel Van LWB

MOT Due 31/08/2026

CAP Clean £9,225.00

CAP Average £7,675.00

CAP Below £5,675.00

Gearbox MANUAL

WARNING LIGHTS ON DASH PENNY SWING LIFT, SIDE LOAD DOOR, TOW BAR.

Tyres

NSF

NSR

OSF


OSR

Spare

Features


- Radio/CD
- Front electric windows

Photos





Condition Check



Damage Photos



1: Dash Warning Lights
Displayed
No Action

2: Seat Base Cover osf
Torn
Over 3mm



3: Bonnet
Dented
With Paint Damage

4: Wing osf
Dented
With Paint Damage



5: Door osf
Dented
With Paint Damage

6: Qtr Panel osr
Dented
With Paint Damage



7: Tailgate
Dented
With Paint Damage

8: Qtr Panel nsr
Rusted
Over 5mm



9: Door nsr
Dented
With Paint Damage

10: Wing nsf
Dented
With Paint Damage



11: Screen Front
Missing
Replace

Interior

Carpet Condition	Average		Upholstery Condition	Average
Seat Condition	Average		Odour	No
Engine Runs	OK		Gearbox 1st and Reverse Test	OK
Brakes	OK		Clutch Slip Test from Static	OK
Turbo Boosting	OK		Gearbox Static Gear Selection (engine running)	OK
Parking Brake	OK		No Excessive Smoking	OK
EML light illuminated	OK		Oil warning light illuminated	OK
Airbag light illuminated	OK		DPF light illuminated	OK
ABS light illuminated	OK		Service indicator light illuminated	OK

Windows

OK

Radio

OK

Steering

OK